

INTISARI

Karya akhir ini dibuat berdasarkan pelaksanaan magang di PT OSHA ASIA, Bogor, Jawa Barat. Lingkup permasalahan yang dijadikan kajian dalam karya akhir ini adalah tentang cara mengatasi miringnya posisi *upper* pada proses *assembling*. Tujuan dari karya akhir ini adalah untuk mengidentifikasi dan menyelesaikan masalah pada pembuatan sepatu *safety* model 3138. Metode yang digunakan adalah pengamatan, wawancara, pengumpulan data dan praktek kerja pada proses *assembling*, di temukan masalah yaitu posisi pada *upper* sepatu tersebut miring sehingga hal tersebut akan mempengaruhi kenyamanan dalam memakai sepatu, masalah tersebut muncul karena dalam pembuatan tanda pada *texson* sepatu tidak terlalu kelihatan, itu menyebabkan pada proses jahitan *stroble* kurang pas. Penyelesaian masalah dapat dilakukan dengan menebalkan lagi tanda pada *texon* sepatu tersebut agar saat di lakukan perakitan *upper* atau jahitan *strobel* agar tidak terjadi kemiringan, dengan hal tersebut sepatu akan lebih nyaman dipakai untuk para pekerja.

Kata kunci: *assembling*, tanda, *upper*, sepatu *safety* model 3138

ABSTRACT

This final work was made based on the implementation of an internship at PT.OSHA ASIA, Bogor, West Java. The scope of the problem that is used as a study in this final paper is about how to overcome the tilt of the upper position in the assembling process. The purpose of this final paper is to identify and solve problems in the manufacture of safety shoes model 3138,. The methods used are observation, interviews, data collection and work practices in the assembling process, found a problem, namely the position of the upper shoe is tilted so that it will be affect the comfort in wearing shoes, this problem arises because in making shoes the marks on the texson shoes are not very visible, it causes the stroble stitching process to not fit properly. The solution to the problem can be done by thickening the texon mark on the shoe so that when the upper or strobel stitches are assembled so there is no slope, this will make the shoes more comfortable for workers to wear.

Keyword: *assembling, sign, upper, shoes 3138.*