

INTISARI

PT Diajeng Arcadia Trimitra merupakan perusahaan di bidang industri perseptuan. Salah satu jenis sepatu yang diproduksi adalah sepatu *pump* merk IVANKA. Proses *lasting* di awali dengan persiapan *upper*. Material yang digunakan pada sepatu *pump* merk IVANKA adalah anyaman raffia. Material yang digunakan sedikit kaku dan material lapis yang digunakan lemas. Permasalahan yang ditemui pada saat pelaksanaan magang di perusahaan berupa kerutan bagian *lining* sepatu pada proses *lasting*. Tujuan dari karya akhir ini adalah untuk mengidentifikasi permasalahan, penyebab, dan serta memberi solusi pada masalah tersebut. Metode pengumpulan data berupa observasi, wawancara, dokumentasi, dan studi pustaka. Dan kemudian menganalisis dengan metode penelitian diskriptif dengan metode eksperimen. Berdasarkan dari hasil pengamatan kerutan bagian *lining* sepatu mengakibatkan tidak nyaman dan mengurangi estetika pada sepatu. Solusi dari penyelesaian masalah tersebut berupa pengurangan bahan bagian bawah *lining upper* dan pada proses *lasting* dengan benar sesuai petunjuk penggerjaan. Hasil penerapan usulan perbaikan sudah jauh berkurang bahkan sudah tidak ada lagi kerutan pada bagian *lining* sepatu.

Kata kunci: *Pump*, Kerutan, *Lining*, Proses *Lasting*.

ABSTRACT

PT Diajeng Arcadia Trimitra is a firm in shoe manufacture industry. The shoes that are producing by IVANKA'S merk pump shoes. The lasting process stated whit upper preparation. The materials used in the IVANKA'S pump shoes is raffia webbing. Material were using a bit stiff and lining material are soft. The main problem in an apperentice program in the company is wrinkle in the lining areas of shoes in the lasting process. The main purpose and results of this work are identifying the problem, coused, and giving salutations to the problems. The method of datas collections are observation, interview, documentation, and literature of studies. And then, analyzing by descriptive and experiment methodology. Based on the results, the stiffs at the lining of shoes, it was made on uncomfortable and decreased the aesthetic of the shoes, the solution to this problem is deducting of the materials under the lining upper and doing the lasting process based on the works instruction. The results of the works are being better before and there are no more wrinkle at the lining of shoes.

Keywords: Pump, Wrinkle, Lining, Lasting Process.